

Accent Curb Appeal

This solid oak double door entryway receives several hours of the brutal afternoon sun on the lower half.

BEFORE



The finish had totally burned off the bottom of the doors allowing the unprotected wood to be exposed to the weather.

The doors were successfully restored to a better than new condition.




CORNERSTONE BUILDING ACCENTS
DECORATIVE DOORS, WINDOWS & MORE

www.cornerstonebuildingaccents.com



Contact us today
for a professional
on-site
consultation

678-360-6883



AFTER